MAINE TURNPIKE AUTHORITY

ADDENDUM NO. 2

CONTRACT 2022.12

BRIDGE REPAIRS ROUTE 1 OFF-RAMP (RAMP J) UNDERPASS (MM 1.50) WILSON ROAD UNDERPASS (MM 2.00) LITTLEFIELD ROAD (MM 17.30)

Make the following changes to the bid documents:

In the Plans, Sheet 2, make the following 'Pen and Ink' change. **CHANGE** the quantity of Item 518.93 – Parapet Repairs from 110 SF to 200 SF.

In the Contract Documents, Proposal, **REMOVE** page P-3 and **REPLACE** with the attached revised page P-3.

| Note: The above items shall be considered as part of th | e bid submittal. |
|---|---|
| <u>Attachments</u> | |
| • Proposal Page P-3 | (1 page) |
| The total number of pages included with this addendum | is three (3). |
| All bidders are requested to acknowledge the receipt of faxing this sheet to Nate Carll, Purchasing Department to acknowledge receipt of this Addendum No. 2 on Pag | , (207) 871-7739. Bidders are also required |
| Business Name | |
| Print Name and Title | |
| Signature | |

May 17, 2022

Date

| Very truly yours, |
|--------------------------|
| MAINE TURNPIKE AUTHORITY |
| |
| |
| Purchasing Manager |
| Maine Turnpike Authority |

CONTRACT NO: 2022.12

| | | 1 | ı | ı | 001 | NIKACI NO. Z | 022.12 | | | |
|------------------|---|----------------|-----------------------|------------------------|--------------------------|-----------------------|--------------|--|--|--|
| Item No | Item Description | Units | Approx. Quantities | Unit Prices in Numbers | | Bid Amount in Numbers | | | | |
| | | | Q | Dollars | Cents | Dollars | Cents | | | |
| BROUGHT FORWARD: | | | | | | | | | | |
| 518.4 | Epoxy Injection Crack Repair | Linear Foot | 90 | | | | | | | |
| 518.48 | Reseal Joints | Linear Foot | 125 | | | | - | | | |
| 518.70 | Repair of Overhead Surfaces < 8 inches | Square Foot | 5 | | : - - | | | | | |
| 518.75 | Fascia and Overhang Repairs | Square Foot | 147 | | - | | | | | |
| 518.76 | Partial Concrete Curb Reconstruction | Linear Foot | 280 | | | | - | | | |
| 518.80 | Partial Depth Concrete Deck Repairs | Square Foot | 515 | | | | | | | |
| 518.81 | Full Depth Concrete Deck Repairs | Square Foot | 175 | | | | | | | |
| 518.864 | Elastomeric Concrete Header Repair | Cubic Foot | 10 | | | | | | | |
| 518.92 | Slope Protection Repairs | Linear Foot | 170 | | - | | | | | |
| 518.921 | Slope Protection Concrete Repairs | Square Foot | 80 | | - | | | | | |
| 518.93 | Parapet Repairs | Square Foot | 200 | | - | | | | | |
| 518.94 | Parapet Surface Repairs | Linear Foot | 361 | | - | | | | | |
| | | I | <u>I</u> | | | | | | | |

| 518.94 | Parapet Surface Repairs | Linear Foot | 361 | | | | | |
|------------------|-------------------------|----------------|-----|--|--|--|--|--|
| CARRIED FORWARD: | | | | | | | | |
| P-3 | | | | | | | | |