



# Maine Turnpike Authority Schedule of Items

## BRIDGE REPAIRS EXIT 102 AND 103 UNDERPASSES MILE MARKERS 102.0 AND 102.5

Item No.	Description	Quantity	UOM
504.801	Interchange 102 Bridge Beam Insert Repair (Repair Area "A")	1.00	LS
505.802	Interchange 102 Bridge Beam Insert Repair (Repair Area "B")	1.00	LS
504.82	Interchange 103 Bridge Beam Gouge Repairs	1.00	LS
506.9103	Zinc Rich Coating System (Field Applied)	1.00	LS
524.30	Temporary Structural Support	1.00	LS
526.306	Temporary Concrete Barrier Type I - Supplied by Authority (280 LF)	1.00	LS
527.341	Work Zone Crash Cushion - TL-3	1.00	EA
531.82	Heat Straightening (Repair Areas "C1", "C2", "D1", "D2", "D3", "E1", E2, and "E3")	1.00	LS
531.83	Additional Heat Straightening	20.00	CH
627.711	White or Yellow Pavement Marking Line - Plan Quantity	2,700.00	LF
627.73	Temporary 6 in Pavement Marking - Tape	7,250.00	LF
627.77	Removing Existing Pavement Marking	1,050.00	SF
629.05	Hand Labor, Straight Time	20.00	HR
631.36	Foreman	10.00	HR
652.30	Flashing Arrow	2.00	EA
652.33	Drum	82.00	EA
652.35	Construction Signs	675.00	SF
652.361	Maintenance of Traffic Control Devices	1.00	EA
652.41	Portable-Changeable Message Sign	1.00	EA
652.45	Truck Mounted Attenuator	1.00	EA
659.10	Mobilization	1.00	LS