

MM 47 Southbound

Flashing 45 Installation

Crews from various Camps assisted with the installation of Flashing 45 Advisory signs at various locations along the Turnpike over the past few months. Eight new Flashing 45s' were installed in 2014. This one is being installed at MM 47.0 southbound.



Various Locations on Turnpike

Ditch Line and Back Slope Mowing

In 2013, the Authority purchased a tractor mounted Boom Mower that allows Highway Maintenance crews to mow roadside vegetation in difficult spots. Ditch lines, steep back slopes and bridge side slopes are mostly within reach now with this piece of equipment.



Mowing next to Coles Hill Road on the northbound.



Ditch line Mowing at MM 31 southbound.