



Maine Turnpike Authority

Schedule of Items

Asphaltic Plug Joint Replacements - Multiple Locations

Item No.	Description	Quantity	UOM
518.5	Repair of Upward Facing Surfaces – to Reinforcing Steel < 8 inches	20.00	SF
520.23	Asphaltic Plug Joint	500.00	LF
659.1	Mobilization	1.00	LS
661.1	Toll Stipend	1.00	LS